



AN ISO/IEC 17020 ACCREDITED INSPECTION BODY

CERTIFICATE OF THOROUGH EXAMINATION AND TEST

Certificate No: O/44483/20/08/20

Date of Inspection: 28/08/2020

Name and Address of the Owner:	TRUCK OMAN EQUIPMENT RENTAL
Maker & Date of Manufacture:	CATERPILLAR ; 2018
Place of Inspection:	FARAH
Ref. Standard:	BS EN 474-3, BS ISO 2330 SP2275
Registration No. & Owner No.:	1428 MA ; TER 1535
Model No. and Serial No.:	930K ; CAT0930KHP3K00631
Running hours:	1978 hrs.
Manufacturer's documentation:	Satisfactory
Date of Previous inspection / cert no:	07/11/19; O/41744/19/11/03
Date of Next inspection:	27/02/2021
Date of Previous load test / cert no:	13/11/2018 ; O/38758/18/11/06
Date of Next load test:	12/11/2022
Availability of operations manual in cabin:	Satisfactory
Availability of daily check report:	Satisfactory

Description

Diesel powered rubber tired hydraulically operated articulated Wheel Loader c/w fork SWL : 5000 kgs @ 500 mm load center.

Test carried out according to tabulated column

Description of test:	Test load applied	S.W.L
	In kgs	In kgs
Visual inspection, Functional test & Performance test carried out.		
Max. Lifting Height: 3907mm		
Hydraulic creep : Nil	5000 Kg	5000 Kg

Conclusion: Fit for its intended use at the time of inspection.

This certificate becomes invalid if any Alteration/Major Repair and modification is done.

This is to certify that the undersigned competent representative, did attend to examine the item described above in accordance to the aforementioned standard. At the time of inspection, the said item were found to be free from flaws, deformations or other defects. The equipment is satisfactory for its intended use within the limits specified and at the time of inspection was found to be satisfactory for further use, provided there is continuous maintenance applied, qualified operators employed and implementation of our remarks and recommendations.

Approved by, Name & Signature: Mr. Gishin Thomas



Inspected by, Name & Signature: Infanso Oswin



Annexure of certificate of test & thorough examination

Certificate No: O/44483/20/08/20

Date of Inspection: 28/08/2020

Description	Condition	Remarks
Tires, rims, wheel bolts and axles	S	
Masts and Back rest , carriage	S	
Forks and its extensions, slide end stopper, locks	S	
Load chain and its assemblies	NA	
Side rollers and roll over cage	S	
Safety devices	NA	
Battery and its connections	S	
Hydraulic system & hoses and end fittings	S	
Electrical system & Cables	S	
Cooling system	S	
Steering function	S	
All controls levers function & symbols legible	S	
Capacity plate in place and legible	S	
All gauges in cab	S	
Over head & foot guard	S	
Exhaust system	S	
Side shifting function (if applicable)	NA	
Horn, reverse alarm, rotating warning light	S	
Lights & indicators	S	
Seat and seat belts	S	
Parking brake and foot brake function	S	
Fire extinguisher	S	
MPI fork blades, date / report nr. (annually)	S	28/08/20; O/44483
Mast disassembly (every 4 years)	NA	
General condition	S	
Display markings (SWL, tire pressure, insp. date, due date)	S	
S- Satisfactory NS-Not Satisfactory NA-Not applicable NP-Not provided by OEM SC- See Comments		
Details of tools/equipments used: STS-VC-7949; STS-LD-63		
General comments: NONE		

Approved by, Name & Signature: Mr. Gishin Thomas



Inspected by, Name & Signature: Infanso Oswin