



الشركة الفنية لخدمات السلامة والفحص الفني ش.م.م
SAFETY TECHNICAL SERVICES AND INSPECTIONS

Tel: +968 24502589, Fax: +968 24590272, Email: stsi@safetyoman.com, Website: www.safetyoman.com
P.O. Box 3288, Airport Heights P.C. 111, Sultanate of Oman.

2
LE
Full N

MAGNETIC PARTICLE INSPECTION REPORT

Date of Thorough Examination: 11/08/2020	Report number: O/44464/20/08/05	Job no: 44464
Name and Address of owner for whom the thorough examination was made: TRUCK OMAN RENTAL SULTANATE OF OMAN		Address of premises at which the examination was made: JIFFNAIN
Method: WET Surface Condition: Acceptable	Material: Carbon Steel Equipment: Permanent magnet Yoke	Test temperature: Ambient
Area Inspected (tick the appropriate box): <input checked="" type="checkbox"/> Weldment areas <input type="checkbox"/> Stress Areas <input type="checkbox"/> Full Body <input type="checkbox"/> Others		
WHITE CONTRAST PAINT: Magnavis WCP	MAGNETISING METHOD: Wet suspension black ink	
BLACK MAGNETIC INK: Magnaflux 7HF	ACCEPTANCE CODE: ASME V ARTICLE 7, ASTM E709, AWS D1.1	
Description and identification of the equipment		
<u>KING PIN AND FILLET WELD</u>		
Size : 3.5"		
Trailer Reg: 4760 MR		
Owner ID No. : PLM 1642		
<input checked="" type="checkbox"/> shaped cylindrical king pin. Top head 114mmØ Intermediate 89mmØ Bottom head 111mmØ		
Qty: 1 no		
Date of Last MPI/ Cert No(If any): N/A		
Result of the above test :		
MPI TEST CARRIED OUT SATISFACTORILY, FOUND NO RELEVANT INDICATIONS AT THE TIME OF INSPECTION		
Inspected by, Name & Signature : Koshy Mathew		Latest date by which next MPI r be carried out: 10/08/2021
Qualification : ASNT L2		
Name and address of employer of persons making and authenticating this report:		
Address: SAFETY TECHNICAL SERVICES AND INSPECTIONS P.O. Box 3288, Airport Heights PC 111 Sultanate of Oman. lifting@safetyoman.com		

