




الشركة الفنية لخدمات السلامة والفحص الفني ش.م.م SAFETY TECHNICAL SERVICES AND INSPECTIONS

Tel :+968 24502589, Fax : +968 24590272. Email: stsi@safetyoman.com, Website: www.safetyoman.com
P.O. Box 3288, Airport Heights P.C. 111, Sultanate of Oman.



MAGNETIC PARTICLE INSPECTION REPORT

Date of Thorough Examination: 14/10/2025	Report number: MN/5338/25/10/14	Job no: 5338
Name and Address of the Owner of the Equipment TRUCK OMAN EQUIPMENT RENTAL LLC SULTANATE OF OMAN	Address of premises at which the examination was made: ADAM	
Method: WET Surface Condition: Acceptable	Material: Carbon Steel Equipment: Permanent magnet Yoke	Test temperature: Ambient
Area Inspected (tick the appropriate box): <input type="checkbox"/> Weldment areas <input type="checkbox"/> Stress Areas <input type="checkbox"/> Full Body <input checked="" type="checkbox"/> Others [TOP SURFACE ONLY]		
WHITE CONTRAST PAINT: Magnavis WCP	MAGNETISING METHOD: Wet suspension black ink	
BLACK MAGNETIC INK: Magnaflux 7HF	ACCEPTANCE CODE: ASME V ARTICLE 7, ASTM E709, AWS D1.1	
Description and identification of the equipment: <u>FIFTH WHEEL</u> Make: JOST Type: JSK 38C Serial No.: 13352185 63 FLEET NO: TO 1065 REGISTRATION: 8965 HK Qty: 1 no Date of Last MPI/ Cert No (If any): MP/1210/25/04/002		
Result of the above test: MPI TEST CARRIED OUT SATISFACTORILY, FOUND NO RELEVANT INDICATIONS AT THE TIME OF INSPECTION		
Inspected by, Name & Signature: MIDHUN CS Qualification: ASNT L2		Latest date by which next MPI must be carried out: 13/04/2026
Name and address of employer of persons making and authenticating this report: Address: SAFETY TECHNICAL SERVICES AND INSPECTIONS P.O. Box 3288. Airport Heights PC 111 Sultanate of Oman. lifting@safetyoman.com		