



الشركة الفنية لخدمات السلامة والفحص الفني ش.م.م.
SAFETY TECHNICAL SERVICES AND INSPECTIONS

Tel : +968 24502589, Fax : +968 24590272, Email: stsi@safetyoman.com, Website: www.safetyoman.com
P.O. Box 3288, Airport Heights P.C. 111, Sultanate of Oman.



MAGNETIC PARTICLE INSPECTION REPORT

| | | |
|---|--|---|
| Date of Thorough Examination: 20/12/2020 | Report number: O/44991/20/12/01 | Job no: 44991 |
| Name and Address of owner for whom the thorough examination was made: TRUCK OMAN EQUIPMENT RENTAL SULTANATE OF OMAN | | Address of premises at which the examination was made: JIFNAIN |
| Method: WET Surface Condition: Acceptable | Material: Carbon Steel Equipment: Permanent magnet Yoke | Test temperature: Ambient |
| Area Inspected (tick the appropriate box): <input type="checkbox"/> Weldment areas <input type="checkbox"/> Stress Areas <input type="checkbox"/> Full Body <input checked="" type="checkbox"/> Others [TOP SURFACE ONLY] | | |
| WHITE CONTRAST PAINT: Magnavis WCP | MAGNETISING METHOD: Wet suspension black ink | |
| BLACK MAGNETIC INK: Magnaflux 7HF | ACCEPTANCE CODE: ASME V ARTICLE 7, ASTM E709, AWS D1.1 | |
| Description and identification of the equipment: <u>FIFTH WHEEL</u> MAKE: JOST TYPE: JSK38C SERIAL NO: 13362150-63 REG NO: 4199 YD / TR-1069 | | |
| Qty: 1 no. | | |
| Date of Last MPI/ Cert No(If any):N/A | | |
| Result of the above test : MPI TEST CARRIED OUT SATISFACTORILY, FOUND NO RELEVANT INDICATIONS AT THE TIME OF INSPECTION | | |
| Inspected by, Name & Signature : Koshy Mathew | | Latest date by which next MPI must be carried out: 19/12/2021 |
| Qualification : ASNT L2 | | |
| Name and address of employer of persons making and authenticating this report: Address: SAFETY TECHNICAL SERVICES AND INSPECTIONS P.O. Box 3288. Airport Heights PC 111 Sultanate of Oman. lifting@safetyoman.com | | |

For certificate authenticity or for further clarifications, please contact us at stsi@safetyoman.com

A part of SAFETY technical SERVICES LLC

