

## MAGNETIC PARTICLE INSPECTION REPORT

Date of Thorough Examination: 19/09/2023	Report number: MP/51297/23/09/03	Job no: 51297
Name and Address of owner for whom the thorough examination was made:  TRUCK OMAN EQUIPMENT RENTAL LLC SULTANATE OF OMAN		Address of premises at which the examination was made:  ADAM
Method: WET Surface Condition: Acceptable	Material: Carbon Steel Equipment: Permanent magnet Yoke	Test temperature: Ambient
Area Inspected ( tick the appropriate box):  <input type="checkbox"/> Weldment areas <input type="checkbox"/> Stress Areas <input type="checkbox"/> Full Body <input checked="" type="checkbox"/> Others [ TOP SURFACE]		
WHITE CONTRAST PAINT: Magnavis WCP	MAGNETISING METHOD: Wet suspension black ink	
BLACK MAGNETIC INK: Magnaflux 7HF	ACCEPTANCE CODE: ASME V ARTICLE 7 , ASTM E709 ,AWS D1.1	
Description and identification of the equipment:		
<u>Fifth Wheel</u> <b>Make:</b> Jost <b>Type:</b> JSK 38C <b>Serial no:</b> 13362150-63 <b>Owner id:</b> TER 1069 <b>Reg no:</b> 4199 YD		
<b>Qty:</b> 1 no <b>Date of Last MPI/ Cert No( If any):</b> 13/09/2022;A/49866		
<b>Result of the above test :</b> <b>MPI TEST CARRIED OUT SATISFACTORILY, FOUND NO RELEVANT INDICATIONS AT THE TIME OF INSPECTION</b>		
Inspected by, Name & Signature : MADHU PILLAI		Latest date by which next MPI must be carried out: 18/09/2024
Qualification : ASNT L2		
Name and address of employer of persons making and authenticating this report:  Address: SAFETY TECHNICAL SERVICES AND INSPECTIONS P.O. Box 3288. Airport Heights PC 111 Sultanate of Oman. <a href="mailto:lifting@safetyoman.com">lifting@safetyoman.com</a>		

