الشركة الفنية لخدمات السلامة والفحص الفني ش.م.م
SAFETY TECHNICAL SERVICES AND INSPECTIONS
Tel :+968 24502589, Fax : +968 24590272. Email: stsi@safetyoman.com, Website: www.safetyoman.com
P.O. Box 3288, Airport Heights P.C. 111, Sultanate of Oman.

LEEA Full Member

MAGNETIC PARTICLE INSPECTION REPORT

Date of Thorough Examination: 10/12/2020	Report number: V/45607/20/12/02	Job no: 45607
Name and Address of owner for whom the thorough examination was made: **TRUCK OMAN EQUIPMENT RENTAL SULTANATE OF OMAN**	**Address of premises at which the examination was made:** **JIFFNAIN**	
Method: WET **Material: Carbon Steel** **Test temperature: Ambient** **Surface Condition: Acceptable** **Equipment: Permanent magnet Yoke**		
Area Inspected (tick the appropriate box): ☐ Weldment areas ☐ Stress Areas ☐ Full Body ☑ Others [TOP SURFACE ONLY]		
WHITE CONTRAST PAINT: Magnavis WCP	**MAGNETISING METHOD: Wet suspension black ink**	
BLACK MAGNETIC INK: Magnaflux 7HF	**ACCEPTANCE CODE: ASME V ARTICLE 7 , ASTM E709 ,AWS D1.1**	
Description and identification of the equipment: **FIFTH WHEEL** **Make : JOST** **Type : JSK 38 C** **Serial No. : NA** **Reg. No. : 4876 M.D / TER 1071** **Qty: 1no.** Date of Last MPI/ Cert No(If any):N/A		
Result of the above test : **MPI TEST CARRIED OUT SATISFACTORILY, FOUND NO RELEVANT INDICATIONSAT THE TIME OF INSPECTION**		

Inspected by, Name & Signature : Koshy Mathew Qualification : ASNT L2		Latest date by which next MPI must be carried out: 09/12/2021
Name and address of employer of persons making and authenticating this report: Address: SAFETY TECHNICAL SERVICES AND INSPECTIONS P.O. Box 3288. Airport Heights PC 111 Sultanate of Oman. lifting@safetyoman.com		