

الشركة الفنية لخدمات السلامة والفحص الفني ش.م.م.

SAFETY TECHNICAL SERVICES AND INSPECTIONS

Tel : +968 24502589, Fax : +968 24590272. Email: stsi@safetyoman.com, Website: www.safetyoman.com
P.O. Box 3288, Airport Heights P.C. 111, Sultanate of Oman.



MAGNETIC PARTICLE INSPECTION REPORT

Date of Thorough Examination: 30/05/2022	Report number: MP/48919/22/05/01	Job no: 48919
Name and Address of the Owner of the Equipment TRUCK OMAN EQUIPMENT RENTAL LLC SULTANATE OF OMAN		Address of premises at which the examination was made: JUFFNAIN
Method: WET Surface Condition: Acceptable	Material: Carbon Steel Equipment: Permanent magnet Yoke	Test temperature: Ambient
Area Inspected (tick the appropriate box): <input type="checkbox"/> Weldment areas <input type="checkbox"/> Stress Areas <input type="checkbox"/> Full Body <input checked="" type="checkbox"/> Others		
WHITE CONTRAST PAINT: Magnavis WCP	MAGNETISING METHOD: Wet suspension black ink	
BLACK MAGNETIC INK: Magnaflux 7HF	ACCEPTANCE CODE: ASME V ARTICLE 7 , ASTM E709 ,AWS D1.1	
Description and identification of the equipment: <u>FIFTH WHEEL</u>		
Make : JOST		
Model: JSK38C		
Serial no: 1336214763		
Reg: 8467 MK		
Owner id; TER 1072		
Qty: 1nos		
Date of Last MPI/ Cert No(If any): 01/03/20; K/42672/02		
Result of the above test :		
MPI TEST CARRIED OUT SATISFACTORILY, FOUND NO RELEVANT INDICATIONS AT THE TIME OF INSPECTION		

Inspected by, Name & Signature : MADHU PILLAI		Latest date by which next MPI must be carried out: 29/05/2023
Qualification : ASNT L2		
Name and address of employer of persons making and authenticating this report: Address: SAFETY TECHNICAL SERVICES AND INSPECTIONS P.O. Box 3288. Airport Heights PC 111 Sultanate of Oman. lifting@safetyoman.com		

