

## MAGNETIC PARTICLE INSPECTION REPORT

Date of Thorough Examination: 27/02/2022	Report number: MO/48365/22/02/01	Job no: 48365
Name and Address of owner for whom the thorough examination was made:  TRUCK OMAN EQUIPMENT RENTAL SULTANATE OF OMAN		Address of premises at which the examination was made:  Ghala
Method: WET Surface Condition: Acceptable	Material: Carbon Steel Equipment: Permanent magnet Yoke	Test temperature: Ambient
Area Inspected ( tick the appropriate box):  <input type="checkbox"/> Weldment areas <input type="checkbox"/> Stress Areas <input type="checkbox"/> Full Body <input checked="" type="checkbox"/> Others [TOP SURFACE ONLY]		
WHITE CONTRAST PAINT: Magnavis WCP	MAGNETISING METHOD: Wet suspension black ink	
BLACK MAGNETIC INK: Magnaflux 7HF	ACCEPTANCE CODE: ASME V ARTICLE 7 , ASTM E709 ,AWS D1.1	
Description and identification of the equipment:		
<p><b>FIFTH WHEEL</b></p> <p>Make : JOST</p> <p>Type : JSK 38C</p> <p>Serial No. : 1335240363</p> <p>Reg. No. : 4875 MD</p> <p>Owner Id: TER 1064</p> <p>Qty: 1no.</p>		
Date of Last MPI/ Cert No( If any):30/11/2020 ,O/44968/20/11/01		
Result of the above test :		
<p><b>MPI TEST CARRIED OUT SATISFACTORILY, FOUND NO RELEVANT INDICATIONS AT THE TIME OF INSPECTION</b></p>		
Inspected by, Name & Signature : Mostafa Mohamed		Latest date by which next MPI must be carried out: 26/02/2023
Qualification : ASNT L2		
Name and address of employer of persons making and authenticating this report:  Address: SAFETY TECHNICAL SERVICES AND INSPECTIONS P.O. Box 3288. Airport Heights PC 111 Sultanate of Oman. <a href="mailto:lifting@safetyoman.com">lifting@safetyoman.com</a>		

