

## MAGNETIC PARTICLE INSPECTION REPORT

Date of Thorough Examination: 18/03/2020	Report number: O/43308/20/03/04	Job no: 43308
Name and Address of owner for whom the thorough examination was made:  TRUCK OMAN EQUIPMENT RENTAL SULTANATE OF OMAN		Address of premises at which the examination was made:  JIFFNAIN
Method: WET Surface Condition: Acceptable	Material: Carbon Steel Equipment: Permanent magnet Yoke	Test temperature: Ambient
Area Inspected ( tick the appropriate box):  <input type="checkbox"/> Weldment areas <input checked="" type="checkbox"/> Stress Areas <input type="checkbox"/> Full Body <input type="checkbox"/> Others		
WHITE CONTRAST PAINT: Magnavis WCP	MAGNETISING METHOD: Wet suspension black ink	
BLACK MAGNETIC INK: Magnaflux 7HF	ACCEPTANCE CODE: ASME V ARTICLE 7 , ASTM E709 ,AWS D1.1	
Description and identification of the equipment:		
<p><b>FIFTH WHEEL</b></p> <p>Make: JOST</p> <p>Type: JSK 38 C1</p> <p>Serial No: U36 1314361163</p> <p>Reg No: 3994 HW</p> <p>Owner fleet no: TER 1060</p> <p>Qty: 2 no</p>		
Date of Last MPI/ Cert No( If any): n/a		
Result of the above test :		
<b>MPI TEST CARRIED OUT SATISFACTORILY, FOUND NO RELEVANT INDICATIONS AT THE TIME OF INSPECTION</b>		
Inspected by, Name & Signature : Infanso oswin		Latest date by which next MPI must be carried out:  After one year as per client requirement or at the discretion of lifting inspector
Qualification : ASNT L2		
Name and address of employer of persons making and authenticating this report:  Address: SAFETY TECHNICAL SERVICES AND INSPECTIONS P.O. Box 3288. Airport Heights PC 111 Sultanate of Oman. <a href="mailto:lifting@safetyoman.com">lifting@safetyoman.com</a>		

