

TEB-1060

TRUCKMAN EQUIPMENT RENTAL LLC	Jan
	Feb
	Apr
	May
	Jun
	Jul
	Aug
	Sep
	Oct
	Nov
	Dec

**BLACK TOP & GRADED
ROADS**

INSPECTION No.: 241

REG No: 3994 HW

CONTRACT: N/A

OWNER: TRUCKMAN

INSPDATE: 18.03.2020

NEXT INSP: 17.03.2021

INSPECTED BY: S. Phil

'20	')	'22	'23	
-----	----	-----	-----	--



TRUCKOMAN
EQUIPMENT RENTAL LLC

Petroleum Development Oman LLC

TF 30



SAFETY INSPECTION REPORT SR No.: H **0209**

HEAVY GOODS VEHICLE (Kerb Weight greater than 4000kg)	
Owner : <i>TRUCK OMAN</i>	Vehicle Type and Model : <i>MAN P/mixer</i>
Fleet Number : <i>TFR-106</i>	Registration No. : <i>3994HW</i>
Odometer Reading : <i>13966</i>	Inspection Date : <i>18.03.2020</i>
Valid ROP Registration : <i>30.03.2020</i>	HAZMAT LICENSE/PRESSURE VESSEL CERTIFICATE VALID IF RELEVANT <i>N/A</i>
Current User (Ref. Ind. If applicable) : <i>N/A</i>	Inspected At : <i>Jiffywash workshop</i>
No. of PDO Spec. Used : <i>SP-2006</i> (for First Use inspection only)	Contract Number : if applicable <i>N/A</i>
	Contract Holder (Ref Ind.) : If applicable <i>N/A</i>

PART 1: CHECKLIST FOR INSPECTION

In Status column, enter ✓ - Pass * - Fail

* = if required or applicable. Shaded box = according to contract or operation requirements.
Numbers in italics, in second column, refer to UK Dept of Transport LGV Inspection Manual checkpoints.

		STATUS	DEFECT FOUND	RE-CHECKED
01	3	Seat belts		
02	5	Smoke emission		
03	6	Road wheels and hubs	✓	
04	7	Tyres, size and type	✓	<i>Michelin 12 R24</i>
05	8	Tyres condition	✓	
06	9	Side guards, under-run guards, bumpers	✓	
07	10	Spare wheel, Jack, tools	✓	
08	11	Trailer coupling	✓	
09	14	Mudguards	✓	
10	15	Cab mountings	✓	
11	16	Cab doors	✓	
12	17	Cab floor and steps	✓	
13	18	Seats	✓	
14	19	Bodywork, load area, headboard	✓	
15	22	Mirrors	✓	
16	23	Windscreen, glass, vision	✓	
	24			
17	25	Windscreen, wipers, washers	✓	
18	26	Speedometer	✓	
19	27	Horn	✓	

HEAVY GOODS VEHICLE continued


28	Driving Controls	✓		
29	Tachograph or IVMS	✓		
30	Steering wheel, column	✓		
31				
32				
33	34 Pressure/Vacuum warning	✓		
24	35 Pressure/Vacuum build up	✓		
25	36 Mechanical brake lever	✓		
26	37 Service brake pedal	✓		
27	38 Service brake operation	✓		
28	39 Hand brake control valves	✓		
29	41 Chassis, sub-frame	✓		
30	42 Electrical equipment,wiring	✓		
31	43 Engine, transmission mountings	✓		
32	44 Oil leaks	✓		
33	45 Fuel tank(s) and systems	✓		
34	46 Exhaust	✓		
35	48,49, Suspension	✓		
	50			
36	51 Shock absorbers	✓		
37	53 Axles, wheels bearings	✓		
38	54 Steering assembly	✓		
55				
56				
39	57 Transmission	✓		
40	59 Mechanical brake components	✓		
41	60 Brake actuators	✓		
42	61 Brake system and components	✓		
43	62 Rear markings	✓		
44	63 Position lamps	✓		
	64			
45	65 Reflectors	✓		
46	66 Indicators	✓		
47	67 Headlamps aim	✓		
48	68 Headlamps	✓		
49	69 Brake Lights	✓		
50	71 Service Brake performance	✓		
51	72 Service Brake performance	✓		
52	73 Parking Brake performance	✓		
53	Reversing alarm	✓		
54	High intensity rear lights	✓		
55	Revolving lights	✓		
56	A/C unit	✓		
57	Fire extinguisher for cab	✓	17.06.2020	
58	Fire extinguisher for load	✓	17.08.2020	
59	First aid kit	✓	With driver hand	
60	Hazard warning Trangles	✓		
61	Winch : General condition			
62	Slings			
63	Oilfield Head board			
64	Speed limiter			
65	Fluid levels			

MISCELLANEOUS ITEMS

Enter details on lines below

66	Tippers : ram operation, oil leaks *			
67	Tippers : hinge shaft and bearings *			
68	Radio Cassette Player	✓		
69				
70				
71				
72				

Part 2: Defect Information, must be attached as the next page, and signed off by the vehicle inspector

 - 18/03/2020