


MAGNETIC PARTICLE INSPECTION REPORT

Date of Thorough Examination: 16/03/2022	Report number: O/48814/22/03/05	Job no: 48814
Name and Address of the Owner of the Equipment TRUCK OMAN EQUIPMENT RENTAL SULTANATE OF OMAN		Address of premises at which the examination was made: JIFFNAIN
Method: WET Surface Condition: Acceptable	Material: Carbon Steel Equipment: Permanent magnet Yoke	Test temperature: Ambient
Area Inspected (tick the appropriate box): <input type="checkbox"/> Weldment areas <input type="checkbox"/> Stress Areas <input type="checkbox"/> Full Body <input checked="" type="checkbox"/> Others [TOP SURFACE ONLY]		
WHITE CONTRAST PAINT: Magnavis WCP	MAGNETISING METHOD: Wet suspension black ink	
BLACK MAGNETIC INK: Magnaflux 7HF	ACCEPTANCE CODE: ASME V ARTICLE 7 , ASTM E709 ,AWS D1.1	
Description and identification of the equipment:		
<p>FIFTH WHEEL</p> <p>Make : Jost</p> <p>Type : JSK 38C</p> <p>Serial No. : 1341506463</p> <p>Reg. No. : 4431 RK / TER 1080</p>		
<p>Qty: 1no.</p> <p>Date of Last MPI/ Cert No(If any):N/A</p> <p>Result of the above test :</p> <p>MPI TEST CARRIED OUT SATISFACTORILY, FOUND NO RELEVANT INDICATIONSAT THE TIME OF INSPECTION</p>		
Inspected by, Name & Signature : OSWIN Qualification : ASNT L2		Latest date by which next MPI must be carried out: 15/03/2023
Name and address of employer of persons making and authenticating this report: Address: SAFETY TECHNICAL SERVICES AND INSPECTIONS P.O. Box 3288. Airport Heights PC 111 Sultanate of Oman. lifting@safetyoman.com		

