

## MAGNETIC PARTICLE INSPECTION REPORT

Date of Thorough Examination: 24/03/2022	Report number: MO/48380/22/03/05	Job no: 48380
Name and Address of the Owner of the Equipment  TRUCK OMAN EQUIPMENT RENTAL SULTANATE OF OMAN		Address of premises at which the examination was made:  JIFFNAIN
Method: WET Surface Condition: Acceptable	Material: Carbon Steel Equipment: Permanent magnet Yoke	Test temperature: Ambient
Area Inspected ( tick the appropriate box):  <input type="checkbox"/> Weldment areas <input type="checkbox"/> Stress Areas <input type="checkbox"/> Full Body <input checked="" type="checkbox"/> Others [ Top Surface Only ]		
WHITE CONTRAST PAINT: Magnavis WCP	MAGNETISING METHOD: Wet suspension black ink	
BLACK MAGNETIC INK: Magnaflux 7HF	ACCEPTANCE CODE: ASME V ARTICLE 7 , ASTM E709 ,AWS D1.1	
Description and identification of the equipment:		
<p><b>FIFTH WHEEL</b></p> <p>Make: JOST Type: JSK 38C</p> <p>Serial No: U 36 13436934 63</p> <p>Reg No: 2984 DA</p> <p>Owner Fleet No. : TER 1087</p>		
Qty: 1 no		
Date of Last MPI/ Cert No( If any): 20/12/2020 ; O/44991/20/12/05		
Result of the above test :		
MPI TEST CARRIED OUT SATISFACTORILY, FOUND NO RELEVANT INDICATIONS AT THE TIME OF INSPECTION		
Inspected by, Name & Signature : Mostafa Mohamed		Latest date by which next MPI must be carried out: 23/03/2023
Qualification : ASNT L2		
Name and address of employer of persons making and authenticating this report:  Address: SAFETY TECHNICAL SERVICES AND INSPECTIONS P.O. Box 3288. Airport Heights PC 111 Sultanate of Oman. <a href="mailto:lifting@safetyoman.com">lifting@safetyoman.com</a>		

