



MAGNETIC PARTICLE INSPECTION REPORT

Date of Thorough Examination: 25/03/2019	Report number: MA/39827/19/03/18	Job no: 39827
Name and Address of owner for whom the thorough examination was made: TRUCK OMAN SULTANATE OF OMAN	Address of premises at which the examination was made: SAFAH	
Method: WET Surface Condition: Acceptable	Material: Carbon Steel Equipment: Permanent magnet Yoke	Test temperature: Ambient

Area Inspected (tick the appropriate box):

Weldment areas Stress Areas Full Body Others

WHITE CONTRAST PAINT: Magnavis WCP	MAGNETISING METHOD: Wet suspension black ink
------------------------------------	--

BLACK MAGNETIC INK: Magnaflux 7HF	ACCEPTANCE CODE: ASME V ARTICLE 7 , ASTM E709 ,AWS D1.1
-----------------------------------	---

Description and identification of the equipment:

KING PIN AND FILLET WELD

Make : JOST (3.5")

Trailer Reg: 9268 RH

Fleet no. : TO-2699

[I] shaped cylindrical king pin.

Top head 114mm

Intermediate 89mm

Bottom head 111mm

Qty: 1no.

Date of Last MPI/ Cert No(If any): 07/05/2018 ; O/37502

Result of the above test :

MPI TEST CARRIED OUT SATISFACTORILY, FOUND NO RELEVANT INDICATIONS AT THE TIME OF INSPECTION

Inspected by, Name & Signature : Qualification : ASNT L2	Malik Mohammed 	Latest date by which next MPI must be carried out: 24/03/2020
Name and address of employer of persons making and authenticating this report: SAFETY TECHNICAL SERVICES PO BOX 3288. SEEB. PC 111 MUSCAT. lifting@safetyoman.com		