



# الشركة الفنية لخدمات السلامة والفحص الفني ش.م.م


## SAFETY TECHNICAL SERVICES AND INSPECTIONS

Tel :+968 24502589, Fax : +968 24590272. Email: stsi@safetyoman.com, Website: www.safetyoman.com  
P.O. Box 3288, Airport Heights P.C. 111, Sultanate of Oman.



### MAGNETIC PARTICLE INSPECTION REPORT

Date of Inspection: 06/06/2025	Report number: K/4416/25/06/90	Job no: 4416
Name and Address of the Owner of the Equipment TRUCK OMAN (NORTH) SULTANATE OF OMAN	Address of premises at which the examination was made: HAIMA	
Method: WET Surface Condition: Acceptable	Material: Carbon Steel Equipment: Permanent magnet Yoke	Test temperature: Ambient
Area Inspected ( tick the appropriate box): <input type="checkbox"/> Weldment areas <input checked="" type="checkbox"/> Stress Areas <input type="checkbox"/> Full Body <input type="checkbox"/> Others		
WHITE CONTRAST PAINT: Magnavis WCP	MAGNETISING METHOD: Wet suspension black ink	
BLACK MAGNETIC INK: Magnaflux 7HF	ACCEPTANCE CODE: ASME V ARTICLE 7 , ASTM E709 ,AWS D1.1	
Description and identification of the equipment: <b>IN HOOK MPI</b> Make: SANY Reg No: 1552 MA Main Hook serial no: HCZ 1611001 MAIN HOOK CAPACITY: 75T FLEET NO: TO-2565 Qty: 1 no  Qty: 1 no Date of Last MPI/ Cert No( If any): n/a		
Result of the above test : MPI TEST CARRIED OUT SATISFACTORILY, FOUND NO RELEVANT INDICATIONS AT THE TIME OF INSPECTION		

Inspected by, Name & Signature : Koshy Mathew  Qualification : ASNT L2		Latest date by which next MPI must be carried out:  AFTER ONE YEAR AS PER CLIENT REQUIREMENT OR AT THE DISCRETION OF THE LIFTING INSPECTOR
Name and address of employer of persons making and authenticating this report:  Address: SAFETY TECHNICAL SERVICES AND INSPECTIONS P.O. Box 3288. Airport Heights PC 111 Sultanate of Oman. <a href="mailto:lifting@safetyoman.com">lifting@safetyoman.com</a>	