

MAGNETIC PARTICLE INSPECTION REPORT

| | | |
|--|--|--|
| Date of Thorough Examination: 03/01/2023 | Report number: MP/50592/23/02/02 | Job no: 50592 |
| Name and Address of owner for whom the thorough examination was made: TRUCK OMAN EQUIPMENT RENTAL SULTANATE OF OMAN | | Address of premises at which the examination was made: JIFFNAIN |
| Method: WET Surface Condition: Acceptable | Material: Carbon Steel Equipment: Permanent magnet Yoke | Test temperature: Ambient |
| Area Inspected (tick the appropriate box): <input type="checkbox"/> Weldment areas <input checked="" type="checkbox"/> Stress Areas <input type="checkbox"/> Full Body <input type="checkbox"/> Others | | |
| WHITE CONTRAST PAINT: Magnavis WCP | MAGNETISING METHOD: Wet suspension black ink | |
| BLACK MAGNETIC INK: Magnaflux 7HF | ACCEPTANCE CODE: ASME V ARTICLE 7 , ASTM E709 ,AWS D1.1 | |
| Description and identification of the equipment: | | |
| <p><u>FIFTH WHEEL</u></p> <p>Make: JOST</p> <p>Type: JSK 38 C1</p> <p>Serial No: U36 1351208463</p> <p>Reg No: 2436 HW</p> <p>Owner fleet no: TER 1090</p> <p>Qty: 2 no</p> | | |
| Date of Last MPI/ Cert No(If any): 18/03/2020; O/43308/20/03/03 | | |
| Result of the above test : | | |
| MPI TEST CARRIED OUT SATISFACTORILY, FOUND NO RELEVANT INDICATIONS AT THE TIME OF INSPECTION | | |

| | | |
|--|---|--|
| Inspected by, Name & Signature: Madhu Pillai |  | Latest date by which next MPI must be carried out: After one year as per client requirement or at the discretion of lifting inspector |
| Qualification: ASNT L2 | | |
| Name and address of employer of persons making and authenticating this report: Address: SAFETY TECHNICAL SERVICES AND INSPECTIONS P.O. Box 3288. Airport Heights PC 111 Sultanate of Oman. lifting@safetyoman.com | |  |

