

MAGNETIC PARTICLE INSPECTION REPORT

Date of Thorough Examination: 04/01/2023	Report number: MP/49841/23/01/09	Job no: 49841
Name and Address of the Owner of the Equipment TRUCK OMAN NORTH SULTANATE OF OMAN		Address of premises at which the examination was made: HAIMA
Method: WET Surface Condition: Acceptable	Material: Carbon Steel Equipment: Permanent magnet Yoke	Test temperature: Ambient

Area Inspected (tick the appropriate box):

Weldment areas Stress Areas Full Body Others [TOP SURFACE ONLY]

WHITE CONTRAST PAINT: Magnavis WCP	MAGNETISING METHOD: Wet suspension black ink
BLACK MAGNETIC INK: Magnaflux 7HF	ACCEPTANCE CODE: ASME V ARTICLE 7 , ASTM E709 ,AWS D1.1

Description and identification of the equipment:

FIFTH WHEEL

Make: JOST

Type: JSK 38C

Serial No.: 10060292

Reg. No.: 9443 BA

Owners ID: TO 2029

Qty: 1no.

Date of Last MPI/ Cert No(If any): 06/01/2022; MP/48101/22/01/02

Result of the above test:

MPI TEST CARRIED OUT SATISFACTORILY, FOUND NO RELEVANT INDICATIONS AT THE TIME OF INSPECTION

Inspected by Name & Signature: Madhu Pillai		Latest date by which next MPI must be carried out: 03/01/2024
Qualification: ASNT L2		
Name and address of employer of persons making and authenticating this report: Address: SAFETY TECHNICAL SERVICES AND INSPECTIONS P.O. Box 3288. Airport Heights PC 111 Sultanate of Oman. lifting@safetyoman.com		

