

## MAGNETIC PARTICLE INSPECTION REPORT

|   |  |   |
|---|--|---|
| Date of Thorough Examination:<br>13/06/2021   | Report number:<br>GTK/46921/21/06/02                       | Job no:<br>46921  |
| Name and Address of the Owner of the Equipment<br><br>TRUCK OMAN<br>SULTANATE OF OMAN   |  | Address of premises at which the examination was made:<br><br>BAHJA |
| Method: WET<br>Surface Condition: Acceptable  | Material: Carbon Steel<br>Equipment: Permanent magnet Yoke | Test temperature: Ambient   |
| Area Inspected ( tick the appropriate box):<br><br><input type="checkbox"/> Weldment areas <input checked="" type="checkbox"/> Stress Areas <input checked="" type="checkbox"/> Full Body <input type="checkbox"/> Others |  |   |
| WHITE CONTRAST PAINT: Magnavis WCP  | MAGNETISING METHOD: Wet suspension black ink               |   |
| BLACK MAGNETIC INK: Magnaflux 7HF   | ACCEPTANCE CODE: ASME V ARTICLE 7 , ASTM E709 ,AWS D1.1    |   |
| Description and identification of the equipment:<br><br><u>LORRY LOADER HOOK MPI</u>  |  |   |
| Owner ID No. : TER-1423   |  |   |
| Crane Make : FERRARI  |  |   |
| Model : F 550A1   |  |   |
| Serial No. : 107174   |  |   |
| Reg. No. : 1215 WB  |  |   |
| Qty: 1no  |  |   |
| Date of Last MPI/ Cert No( If any): N/A   |  |   |
| Result of the above test :<br><br><b>MPI TEST CARRIED OUT SATISFACTORILY, FOUND NO RELEVANT INDICATIONS AT THE TIME OF INSPECTION</b>   |  |   |

|  |   |  |
|--|---|--|
| Inspected by, Name & Signature :<br>Vijeesh Ravi   |  | Latest date by which next MPI must be carried out:<br><br>After One Year As Per Client Requirement Or At The Discretion Of Lifting Inspector |
| Qualification : ASNT L2  |   |  |
| Name and address of employer of persons making and authenticating this report:<br><br>Address: SAFETY TECHNICAL SERVICES AND INSPECTIONS<br>P.O. Box 3288. Airport Heights PC 111 Sultanate of Oman.<br><a href="mailto:lifting@safetyoman.com">lifting@safetyoman.com</a> |   |   |

