

CERTIFICATE OF TEST & THOROUGH EXAMINATION OF LORRY LOADING CRANE
Certificate No: AG/TPI/3717/19
Date of Inspection: 22/07/2019

Name and Address of the Owner:	Truck Oman North LLC Sultanate Of Oman
Maker & Year of Manufacture:	Ferrari, 2019
Place of Inspection:	Misfah
Ref. Standard:	BS7121:2-4:2013 / SP:2275:2019 Rev.01
Registration No. & Owner No.:	Chassis No. K019040
Model and Serial No.:	F550-A1, 107172
Nr. of running hours and/or km read out:	KM: 185
Date of Previous inspection / cert. no:	NEW
Date of Next inspection :	21/07/2020
Date of Previous load test / cert. no:	NEW
Date of Next load test:	21/07/2023
Availability of operations manual	Available
Load Chart	Available
Maintenance records / major repairs carried out:	Available

Description of Crane: Diesel Powered hydraulic telescopic knuckle boom lorry loading crane mounted on flat bed truck, boom length is 2.14mtr to 5mtr, the maximum capacity is 1.8ton @ 2.45 mtr radius

Description of test: Full functional and Load test carried out as per tabulated column.	Boom length	Radius	Test load	Safe working load
	Mtr	Mtr	tonne	KG
Load cell (if available) cert.: Calibrated load used.	3.65	3.65	1.2	1285 Kg.
Note: Always refer to manufacturer manual for the safe operation. Examine the equipment and lifting gears before each use. Never exceed the rated capacity.	5	5	1	945 Kg.

Conclusion: Fit for its intended use
Inspected By: Prasanth PG

Signature:
Date: 22/07/2019

Authenticated By: O.Sunaz

Signature:
Date: 22/07/2019


ANNEXURE OF CERTIFICATE OF TEST & THOROUGH EXAMINATION OF LORRY LOADING CRANE

Certificate No: AG/TPI/3717/19

Date of Inspection: 22/07/2019

Description	Condition	Remarks
Safe load indicator or Load meter /calibration verified	Not applicable	
Level indicator	Satisfactory	
Battery and its connections	Satisfactory	
PTO (Power Take Off) correct operation	Satisfactory	
Telescopic boom extensions/ Boom pads/ Rope guides	Satisfactory	
Hoist winch/ Hoist drum / Correct spooling(if applicable)	Not applicable	
Hoist wire ropes and termination(if applicable)	Not applicable	
Outriggers / beams / jacks / pads	Satisfactory	
Tires / rims / wheel bolts	Satisfactory	
Swing bearing/ -wear / report	See remarks	New
Hook block system/Safety catch	Satisfactory	
Hook MPI, certificate no (Required every 4 yrs)	See remarks	New
Sheaves (Boom & Hook) (if applicable)	Not applicable	
Control levers /Wind shields / Mirrors	Satisfactory	
Over winding alarm or Anti 2 block (if applicable)	Not applicable	
All fasteners /Bolts / Safety pins	Satisfactory	
Electrical System	Satisfactory	
Hydraulic System(Hoses& fitting leakages)	Satisfactory	
Caution rotary light	Satisfactory	
Reverse Horn / Light	Satisfactory	
Fire extinguisher	Satisfactory	
General condition (structural integrity/functionality)	Satisfactory	
Display marking (SWL/tyre pressure/ insp.date/due date)	See Remarks	Dates to be marked

General comments: The equipment is safe for its intended use within the limits specified, provided there is continuous maintenance applied and qualified operators employed.

Inspected By: Prasanth PG



Signature:

Date: 22/07/2019

Authenticated By: O.Sunaz



Signature:

Date: 22/07/2019

