

MAGNETIC PARTICLE INSPECTION REPORT

Date of Inspection: 07/02/2022	Report number: MP/48120/22/02/61	Job no: 48120
Name and Address of the Owner of the Equipment TRUCK OMAN SULTANATE OF OMAN		Address of premises at which the examination was made: Adam
Method: WET Surface Condition: Acceptable	Material: Carbon Steel Equipment: Permanent magnet Yoke	Test temperature: Ambient
Area Inspected (tick the appropriate box): <input type="checkbox"/> Weldment areas <input type="checkbox"/> Stress Areas <input type="checkbox"/> Full Body <input checked="" type="checkbox"/> Others [TOP SURFACE ONLY]		
WHITE CONTRAST PAINT: Magnavis WCP	MAGNETISING METHOD: Wet suspension black ink	
BLACK MAGNETIC INK: Magnaflux 7HF	ACCEPTANCE CODE: ASME V ARTICLE 7 , ASTM E709 ,AWS D1.1	
Description and identification of the equipment:		
<p>FIFTH WHEEL</p> <p>Make : JOST</p> <p>Type : JSK 38 C1</p> <p>Serial No. : 2163260829</p> <p>REG NO - 1503ML</p> <p>OWNERS ID - TO 2000</p>		
Qty: 1no.		
Date of Last MPI/ Cert No(If any): 12/02/2021; K/46002/21/02/06		
Result of the above test :		
MPI TEST CARRIED OUT SATISFACTORILY, FOUND NO RELEVANT INDICATIONSAT THE TIME OF INSPECTION		
Inspected by, Name & Signature : Madhu Pillai		Latest date by which next MPI must be carried out: 06/02/2023
Qualification : ASNT L2		
Name and address of employer of persons making and authenticating this report: Address: SAFETY TECHNICAL SERVICES AND INSPECTIONS P.O. Box 3288. Airport Heights PC 111 Sultanate of Oman. lifting@safetyoman.com		

