




# الشركة الفنية لخدمات السلامة والفحص الفني ش.م.م


## SAFETY TECHNICAL SERVICES AND INSPECTIONS

Tel :+968 24502589, Fax : +968 24590272. Email: stsi@safetyoman.com, Website: www.safetyoman.com  
P.O. Box 3288, Airport Heights P.C. 111, Sultanate of Oman.



### MAGNETIC PARTICLE INSPECTION REPORT

Date of Inspection: 24.02.2026	Report number: AT6743.26.02.10	Job no: 6743
Name and Address of the Owner of the Equipment TRUCK OMAN SULTANATE OF OMAN	Address of premises at which the examination was made: HAIMA	
Method: WET Surface Condition: Acceptable	Material: Carbon Steel Equipment: Permanent magnet Yoke	Test temperature: Ambient
Area Inspected (tick the appropriate box): <input checked="" type="checkbox"/> Weldment areas <input type="checkbox"/> Stress Areas <input type="checkbox"/> Full Body <input checked="" type="checkbox"/> Others [TOP SURFACE ONLY]		
WHITE CONTRAST PAINT: Magnavis WCP	MAGNETISING METHOD: Wet suspension black ink	
BLACK MAGNETIC INK: Magnaflux 7HF	ACCEPTANCE CODE: ASME V ARTICLE 7 , ASTM E709 ,AWS D1.1	
Description and identification of the equipment: <b><u>FIFTH WHEEL</u></b> Make: JOST Type: JSK 38 C1 Serial No.: 2163260829 Reg no : 1503 ML Fleet no : TO 2000 <b><u>INSPECTED AREAS</u></b> <ul style="list-style-type: none"><li>• Plate section area</li><li>• Locking jaw area</li><li>• Release handle area</li></ul> Qty: 1no. Date of Last MPI/ Cert No (If any): 29.12.2025 (AT6710.25.12.46)		
		
Result of the above test : MPI TEST CARRIED OUT SATISFACTORILY, FOUND NO RELEVANT INDICATIONS AT THE TIME OF INSPECTION WITNESSED FUNCTIONAL TEST WAS SATISFACTORY		

Inspected by, Name & Signature: Anoop Thankachan		Latest date by which next MPI must be carried out: 23.08.2026
Qualification: ASNT L2		
Name and address of employer of persons making and authenticating this report: Address: SAFETY TECHNICAL SERVICES AND INSPECTIONS P.O. Box 3288, Airport Heights PC 111 Sultanate of Oman. <a href="mailto:lifting@safetyoman.com">lifting@safetyoman.com</a>	