

LIFTING EQUIPMENT INSPECTION CERTIFICATE

Certificate No: AG/TPI/4352/19

Date of Inspection: 25/08/2019

Name & Address of the Owner: Truck Oman North LLC PO Box 367, PC 116. Sultanate Of Oman.		Place of Inspection: Misfah
		Make & Year : BRADEN, 2019
Description	Registration Number	Max line pull of top layer
Truck mounted winch Model No: HP100B-123114/051-01 Serial No: 1854598	5056BA	100,000 lbs
INSPECTED ITEMS		
Securing bolts	Satisfactory	
Wire rope securing arrangement	Satisfactory	
Condition of drum	Satisfactory	
Wire rope	Satisfactory	Ø 1 1/8" (Cert. No. CCR/556/19). ID No. TV - 2219
Winch line tail chain	Satisfactory	
Hook	Satisfactory	
Hydraulic connections	Satisfactory	
Operation of break	Satisfactory	
Operation of winch	Satisfactory	
General Condition	Satisfactory	

Date of Last Examination	Date of Next Examination
New	24/02/2020

This is to certify that the above equipment has been thoroughly examined, function tested and the results of the examination are as shown.

Inspection carried out as per client requirement, BS EN 14492-1:2006+A1:2009 and found satisfactory at the time of inspection.

The equipment is safe for its intended use within the limits specified by the manufacturer and there should be continuous maintenance applied, qualified operators employed.

Inspected by: Prasanth PG



Signature:
Date: 26/08/2019

Authenticated by: Attaullah Khan



Signature:
Date: 26/08/2019

