

MAGNETIC PARTICLE INSPECTION REPORT

| | | |
|---|--|---|
| Date of Inspection: 09/08/2022 | Report number: MP/49803/22/08/24 | Job no: 49803 |
| Name and Address of the Owner of the Equipment TRUCK OMAN NORTH SULTANATE OF OMAN | | Address of premises at which the examination was made: Haima |
| Method: WET Surface Condition: Acceptable | Material: Carbon Steel Equipment: Permanent magnet Yoke | Test temperature: Ambient |
| Area Inspected (tick the appropriate box): <input type="checkbox"/> Weldment areas <input checked="" type="checkbox"/> Stress Areas <input checked="" type="checkbox"/> Full Body <input type="checkbox"/> Others | | |
| WHITE CONTRAST PAINT: Magnavis WCP | MAGNETISING METHOD: Wet suspension black ink | |
| BLACK MAGNETIC INK: Magnaflux 7HF | ACCEPTANCE CODE: ASME V ARTICLE 7 , ASTM E709 ,AWS D1.1 | |
| Description and identification of the equipment: <u>Fork Heel , Upper & Lower Hooks</u> Reg no: 1994 YM Owner id no: TO 2523 Fork Serial no: 2378330 L8 & 2008361 L8 | | |
| Qty: 1 Pair | | |
| Date of Last MPI/ Cert No(If any): 11/08/2021; O/47031/21/08/29 | | |
| Result of the above test : | | |
| MPI TEST CARRIED OUT SATISFACTORILY, FOUND NO RELEVANT INDICATIONS AT THE TIME OF INSPECTION | | |

| | | |
|--|---|--|
| Inspected by, Name & Signature : Madhu Pillai |  | Latest date by which next MPI must be carried out: After One Year As Per Client Requirement Or At The Discretion Of Lifting Inspector |
| Qualification : ASNT L2 | | |
| Name and address of employer of persons making and authenticating this report: Address: SAFETY TECHNICAL SERVICES AND INSPECTIONS P.O. Box 3288. Airport Heights PC 111 Sultanate of Oman. lifting@safetyoman.com |  | |

