



الشركة الفنية لخدمات السلامة والفحص الفني ش.م.م. SAFETY TECHNICAL SERVICES AND INSPECTIONS

Tel : +968 24502589, Fax : +968 24590272. Email: stsi@safetyoman.com, Website: www.safetyoman.com
P.O. Box 3288, Airport Heights P.C. 111, Sultanate of Oman.



CERTIFICATE OF THOROUGH EXAMINATION AND TEST

Certificate No: A/50824/23/02/03

Date of Inspection: 05/02/2023

Name and Address of the Owner:	TRUCK OMAN (NORTH)	
Maker & Date of Manufacture:	CATERPILLAR; 2012	
Place of Inspection:	HAIMA	
Ref. Standard:	BS EN ISO 2330/ BS EN 474-3; SP 2275	
Registration No. & Owner No.:	1994 YM; TO 2523	
Model No. and Serial No.:	930H ; CAT0930HKDHC04112	
Running hours:	13185 Hrs	
Manufacturer 's documentation:	Available	
Date of Previous inspection / cert no:	09/08/2022; MP/49803/22/08/23	
Date of Next inspection:	04/08/2023	
Date of Previous load test / cert no:	09/08/2022; MP/49803/22/08/23	
Date of Next load test:	08/08/2023	
Availability of operations manual in cabin:	Available	
Availability of daily check report:	Available	
Description of Forklift: Diesel powered hydraulic Operated Articulated Wheel Loader C/W Forks SWL on firm & level ground 4394 kg & on rough terrain 3772 kg @ 600 mm load center		
Test carried out according to tabulated column		
Description of test:	Test load applied In kgs	S.W.L In kgs
Visual inspection & Functional test carried out.		
Max. Lifting Height: 3889 mm		
Hydraulic creep: Nil		
Fork serial no: 2736431-L8 & 2729574A-L8		
Bucket serial no: 12100058392 (Capacity 2.7 m ³)		
	---	4394 Kg Firm Level Ground 3296 KG @ Rough Terrain
Conclusion: Fit for its intended use at the time of inspection. / Refer to checklist- Annexure of certificate		
<i>This certificate becomes invalid if any Alteration/Major Repair and modification is done.</i>		
This is to certify that the undersigned competent representative, did attend to examine the item described above in accordance to the aforementioned standard. At the time of inspection, the said item were found to be free from flaws, deformations or other defects. The equipment is satisfactory for its intended use within the limits specified and at the time of inspection was found to be satisfactory for further use, provided there is continuous maintenance applied, qualified operators employed and implementation of our remarks and recommendations.		

Approved by, Name & Signature: **Infanso Oswin**

Inspected by, Name & Signature: **Mohammad Anaz**

Infanso Oswin



Mohammad Anaz



الشركة الفنية لخدمات السلامة والفحص الفني ش.م.م

SAFETY TECHNICAL SERVICES AND INSPECTIONS

Tel : +968 24502589, Fax : +968 24590272. Email: stsi@safetyoman.com, Website: www.safetyoman.com
P.O. Box 3288, Airport Heights P.C. 111, Sultanate of Oman.



ANNEXURE OF CERTIFICATE OF TEST & THOROUGH EXAMINATION

Certificate No: MP/49803/22/08/23

Date of Inspection: 09/08/2022

Status Legend: S- Satisfactory NA-Not applicable F-Findings CF-Critical Findings					
No.	Description	Status	No.	Description	Status
1	Operations Manual/Catalogue	S	17	All gauges in cab	S
2	Monthly Inspection record	S	18	Overhead & foot guard	S
3	Maintenance records	S	19	Exhaust system	S
4	OEM Specification plate	S	20	Side shifting function (if applicable)	NA
5	Tires, rims, wheel bolts and axles	S	21	Horn, reverse alarm, rotating warning light	S
6	Masts and Back rest , carriage	NA	22	Lights & indicators	S
7	Forks and its extensions, slide end stopper, locks	S	23	Seat and seat belts	S
8	Load chain and its assemblies	NA	24	Parking brake and foot brake function	S
9	Side rollers and roll over cage	NA	25	Fire extinguisher	S
10	Safety devices	NA	26	Display markings (SWL, tire pressure, insp. date, due date)	S
11	Battery and its connections	S	27	Full functional test	S
12	Hydraulic system & hoses and end fittings	S	28	Rated load test	S
13	Electrical system & Cables	S	29	Overload test	NA
14	Cooling system	S	30	NDT(If applicable)	S
15	Steering function	S	31	Other Test (If applicable)	NA
16	All controls levers function & symbols legible	S	32	General Condition	S
Details of tools/equipment's used: STS-LD-75,66,80					
Findings/Critical Findings Report					
F/CF	No.	Remarks			
	30	Inspected Date & Cert 09/08/2022 MP/49803			

