


MAGNETIC PARTICLE INSPECTION REPORT

Date of Thorough Examination: 28/02/2021		Report number: O/46104/21/02/50		Job no: 46104	
Name and Address of owner for whom the thorough examination was made: TRUCK OMAN NORTH SULTANATE OF OMAN			Address of premises at which the examination was made: ADAM		
Method: WET Surface Condition: Acceptable		Material: Carbon Steel Equipment: Permanent magnet Yoke		Test temperature: Ambient	
Area Inspected (tick the appropriate box): ☐ Weldment areas ☐ Stress Areas ☐ Full Body ☒ Others [TOP SURFACE ONLY]					
WHITE CONTRAST PAINT: Magnavis WCP			MAGNETISING METHOD: Wet suspension black ink		
BLACK MAGNETIC INK: Magnaflux 7HF			ACCEPTANCE CODE: ASME V ARTICLE 7 , ASTM E709 ,AWS D1.1		
Description and identification of the equipment: <u>FIFTH WHEEL</u> Make : JOST Type: JSK38C Serial no; 1367785863 Reg No: 4066YR Id no: TO 2060 Qty: 1no. Date of Last MPI/ Cert No(If any): 5/03/2020; MP/42145/20/03/44					
Result of the above test : MPI TEST CARRIED OUT SATISFACTORILY, FOUND NO RELEVANT INDICATIONSAT THE TIME OF INSPECTION					

Inspected by, Name & Signature : Koshy Mathew Qualification : ASNT L2		Latest date by which next MPI must be carried out: 27/02/2022
Name and address of employer of persons making and authenticating this report: Address: SAFETY TECHNICAL SERVICES AND INSPECTIONS P.O. Box 3288. Airport Heights PC 111 Sultanate of Oman. lifting@safetyoman.com		

