



HI-TECH INSPECTION SERVICES L.L.C.

P.O.BOX 1809, RUWI, P.C. 112,
SULTANATE OF OMAN
Phone: (+968) 24449092 | 24446444 | 24449010 | 24446414
www.hitechoman.net Email: admin@hitechoman.net



AN ISO / IEC 17020:2012 ACCREDITED INSPECTION BODY

CERTIFICATE OF TEST & THOROUGH VISUAL EXAMINATION OF FORKLIFT

Certificate No. : HITECH/TJN-2022-229/IC/024

Job No. : TJN-2022-229

Date of Inspection : 26/08/2023

Name & Address of the Owner :	M/S.TRUCKOMAN EQUIPMENT RENTAL LLC,SULTANATE OF OMAN		
Make & Date of Manufacture :	HANGCHA GROUP CO.LTD / 07-2020		
Location of Inspection :	SLB-NIZWA,SULTANATE OF OMAN		
Ref. Standard :	BS ISO 3691-2 / BS ISO 2330 / ISO 22915-2 / SP 2275 REV.2		
Registration No. & Owner No. :	3387 LB / TER1536		
Model & Serial No. :	MODEL NO: CPCD100-XRW14 / SERIAL NO: M9BJ01300		
No.of running hours :	4534.3 Hours		
Date of previous inspection / Cert. No.	28/02/2023,K/51126/23/02/01		
Date of next inspection :	25/02/2024		
Date of Previous Load Test Certificate No:	28/02/2023,K/51126/23/02/01		
Date of Next Performance Test:	27/02/2024		
Availability OEM certificate :	YES, AVAILABLE		
Availability of operations manual in cab :	YES, AVAILABLE		
Availability of load chart in cab :	YES, AVAILABLE		
Availability of daily check report :	YES, AVAILABLE		
Hitech Reference Work Instruction :	HITECH-LFT-WI-009-LAPFL-03		
Measuring equipments's used :	SL NO	TOOLS DESCRIPTION	CALIBRATION DUE
	1.	FORK WEAR CALIPER SL NO: HT-FWC-01	25/08/2024
	3.	MEASURING TAPE SL NO: 035206	19/01/2024
Description of Equipment:	DIESEL POWERED HYDRAULIC COUNTER BALANCED FORKLIFT WITH SIDE SHIFTER, SWL: 10000 Kgs @ 600mm LOAD CENTER.		

Description of Test: A Thorough visual and functional test was carried out. Equipment was Operated and Observed thorough all of its motions. No Creep was Observed.

Maxi. Lifting Height: 3500mm

Attachments: - Fork Serial No: 20528 (L), 20526 (R)

Fork Dimensions : 1500mm(L) x 160mm(W) x 85mm (T)

Note:-Always refer to manufacturer manual for safe operation of Forklift. Examine the equipment before each use. Never exceed the rated capacity.

Test Load Applied (in Kgs) | Safe Working Load (in Kgs)

N/A | 10000 Kgs

@ 600 mm Load Center

- Conclusion: The above-mentioned equipment was tested and thoroughly examined and found satisfactory at the time of examination.

Date of Issue: 31/08/2023

Authorized Name: ANSON D'COSTA

Designation: ASST.TECHNICAL MANAGER

Authorized Signature:

Inspector Name: DABLOO.T KUNJAN

Qualification: LIFTING INSPECTOR (NSL)

Inspector Signature:



This certificate becomes invalid if any Alteration / Major Repair and modification is done. The inspection carried out as per regulation 9 of lifting operations and lifting equipment regulation 1998 (LOLER 98)-UK. This is to certify that the above signed HITECH Inspector, did attend to examine the item described above in accordance to the aforementioned standard. At the time of inspection, the said item were found to be free from flaws, deformation or other defects. The liabilities & insurance as per HITECH Inspection Services LLC.

2. ANNEXURE OF CERTIFICATE OF TEST & THOROUGH VISUAL EXAMINATION OF FORKLIFT

Certificate No. : HITECH/TJN-2022-229/IC/024 Job No. : TJN-2022-229 Date of Inspection : 26/08/2023

Status Legend: S-Satisfactory, NA-Not Applicable, F-Findings, CF-Critical Findings

Description	Status	Remarks
Tires, rims, wheel bolts and axles	Satisfactory	
Mast and back rest, carriage	Satisfactory	
Forks and its extensions, slide end stopper, locks	Satisfactory	
Load chain and its assemblies	Satisfactory	
Side rollers and roll over cage	Satisfactory	
Safety devices	Satisfactory	
Battery and its connections	Satisfactory	
Hydraulic system & hoses and end fittings	Satisfactory	
Electrical system & cables	Satisfactory	
Engine compartment	Satisfactory	
Cooling system	Satisfactory	
Steering function	Satisfactory	
All controls lever's function & symbols legible	Satisfactory	
All gauges in cab	Satisfactory	
Overhead & foot guard	Satisfactory	
Exhaust system	Satisfactory	
Side shifting function (if applicable)	Satisfactory	
Operator cab / wind shields / Mirrors	Satisfactory	
Horn, reverse alarm, rotating warning light	Satisfactory	
Light & indicators	Satisfactory	
Seat & seat belts	Satisfactory	
Access ladders / Hand & Guard rails	Satisfactory	
MPI forks blades / report no.	Satisfactory	K/1126/23/02/02, DT:28/02/2023
Fire extinguisher	Satisfactory	
Full functional test	Satisfactory	
Rated load test	Not Applicable	
Overload test	Not Applicable	
Other test (if applicable)	Not Applicable	
OEM Specification plate in place and legible	Satisfactory	
General condition (structural integrity/functionality)	Satisfactory	
Display marking (SWL / tyre pressure/ insp.date/due date)	Satisfactory	Inspection date and next Inspection due date Needs to be marked

3. General comment: The equipment's is safe for its use within the limits specified, provided there is continuous maintenance applied and qualified operators employed. This Certificate covers only the existing configuration of the equipment at the time of examination. Any changes, alteration or modification shall require re-inspection or re-testing.

Date of Issue: 31/08/2023

Authorized Name: ANSON D'COSTA

Designation: ASST.TECHNICAL MANAGER

Authorized Signature: 

Inspector Name: DABLOO.T KUNJAN

Qualification: LIFTING INSPECTOR (NSL)

Inspector Signature: 

