

MAGNETIC PARTICLE INSPECTION REPORT

Date of Thorough Examination: 21/09/2021	Report number: A/46661/21/09/02	Job no: 46661
Name and Address of the Owner of the Equipment TRUCK OMAN EQUIPMENT RENTAL SULTANATE OF OMAN		Address of premises at which the examination was made: FAHUD SCHLUMBERGER, YARD
Method: WET Surface Condition: Acceptable	Material: Carbon Steel Equipment: Permanent magnet Yoke	Test temperature: Ambient
Area Inspected (tick the appropriate box): <input checked="" type="checkbox"/> Weldment areas <input checked="" type="checkbox"/> Stress Areas <input type="checkbox"/> Full Body <input type="checkbox"/> Others		
WHITE CONTRAST PAINT: Magnavis WCP	MAGNETISING METHOD: Wet suspension black ink	
BLACK MAGNETIC INK: Magnaflux 7HF	ACCEPTANCE CODE: ASME V ARTICLE 7 , ASTM E709 ,AWS D1.1	
Description and identification of the equipment:		
<p><u>MPI On Fork Heel & Weldment Area</u></p> <p>Make : Hangcha group Company</p> <p>Reg No: 6395 LD</p> <p>Owner ID No. : TER 1537</p> <p>Fork Owner id: TER-1537-F1 & F2</p>		
<p>Qty: 1 no</p> <p>Date of Last MPI/ Cert No(If any): 05/10/2020 (MU-HS-20-8609/9226/2-BS)</p>		
<p>Result of the above test :</p> <p>MPI TEST CARRIED OUT SATISFACTORILY, FOUND NO RELEVANT INDICATIONS AT THE TIME OF INSPECTION</p>		
Inspected by, Name & Signature : Mohammed Anaz Qualification : ASNT L2		Latest date by which next MPI must be carried out: After One Year As Per Client Requirement Or At The Discretion Of Lifting Inspector
Name and address of employer of persons making and authenticating this report: Address: SAFETY TECHNICAL SERVICES AND INSPECTIONS P.O. Box 3288. Airport Heights PC 111 Sultanate of Oman. lifting@safetyoman.com		

