

الشركة الفنية لخدمات السلامة والفحص الفني ش.م.م.

SAFETY TECHNICAL SERVICES AND INSPECTIONS

Tel : +968 24502589, Fax : +968 24590272. Email: stsi@safetyoman.com, Website: www.safetyoman.com
P.O. Box 3288, Airport Heights P.C. 111, Sultanate of Oman.



MAGNETIC PARTICLE INSPECTION REPORT

Date of Thorough Examination: 14/03/2022	Report number: K/48177/22/03/02	Job no: 48177
Name and Address of owner for whom the thorough examination was made: TRUCKOMAN EQUIPMENT RENTAL LLC SULTANATE OF OMAN		Address of premises at which the examination was made: FAHUD(SCHLUMBERGER YARD)
Method: WET Surface Condition: Acceptable	Material: Carbon Steel Equipment: Permanent magnet Yoke	Test temperature: Ambient
Area Inspected (tick the appropriate box): <input checked="" type="checkbox"/> Weldment areas <input checked="" type="checkbox"/> Stress Areas <input type="checkbox"/> Full Body <input type="checkbox"/> Others		
WHITE CONTRAST PAINT: Magnavis WCP	MAGNETISING METHOD: Wet suspension black ink	
BLACK MAGNETIC INK: Magnaflux 7HF	ACCEPTANCE CODE: ASME V ARTICLE 7 , ASTM E709 ,AWS D1.1	
Description and identification of the equipment:		
<p>Fork Heel Toe & Weldment Area</p> <p>Make: HANGCHA GROUP COMPANY</p> <p>Serial No: 20610</p> <p>Reg No: 6395LD</p> <p>Owner ID : TER 1537</p> <p>Qty: 1 Pair</p>		
Date of Last MPI/ Cert No(If any): 21/09/2021;A/46661/21/09/02		
Result of the above test :		
MPI TEST CARRIED OUT SATISFACTORILY, FOUND NO RELEVANT INDICATIONS AT THE TIME OF INSPECTION		
Inspected by, Name & Signature : Koshy Mathew Qualification : ASNT L2		Latest date by which next MPI must be carried out: After One Year As Per Client Requirement Or At The Discretion Of Lifting Inspector
Name and address of employer of persons making and authenticating this report: Address: SAFETY TECHNICAL SERVICES AND INSPECTIONS P.O. Box 3288. Airport Heights PC 111 Sultanate of Oman. lifting@safetyoman.com		

