


MAGNETIC PARTICLE INSPECTION REPORT

| | | |
|---|--|--|
| Date of Thorough Examination: 10/09/2025 | Report number: AT/5184/25/09/02 | Job no: 5184 |
| Name and Address of owner for whom the thorough examination was made: TRUCK OMAN EQUIPMENT RENTAL LLC SULTANATE OF OMAN | | Address of premises at which the examination was made: ADAM |
| Method: WET Surface Condition: Acceptable | Material: Carbon Steel Equipment: Permanent magnet Yoke | Test temperature: Ambient |
| Area Inspected (tick the appropriate box): <input type="checkbox"/> Weldment areas <input checked="" type="checkbox"/> Stress Areas <input type="checkbox"/> Full Body <input type="checkbox"/> Others | | |
| WHITE CONTRAST PAINT: Magnavis WCP | MAGNETISING METHOD: Wet suspension black ink | |
| BLACK MAGNETIC INK: Magnaflux 7HF | ACCEPTANCE CODE: ASME V ARTICLE 7, ASTM E709, AWS D1.1 | |
| Description and identification of the equipment: <u>Lorry Loader Crane Hook</u> | | |
| Reg No: 9624 WK |  | |
| Owner Id: TER -1355 | | |
| Qty: 01 NO | | |
| Date of Last MPI/ Cert No (If any): A/51587/23/06/20 | | |
| Result of the above test: MPI TEST CARRIED OUT SATISFACTORILY, FOUND NO RELEVANT INDICATIONS AT THE TIME OF INSPECTION | | |

| | | |
|--|---|---|
| Inspected by, Name & Signature: ANOOP |  | Latest date by which next MPI must be carried out: 09/09/2026 |
| Qualification: ASNT L2 | | |
| Name and address of employer of persons making and authenticating this report: Address: SAFETY TECHNICAL SERVICES AND INSPECTIONS P.O. Box 3288. Airport Heights PC 111 Sultanate of Oman. lifting@safetyoman.com | |  |