الشركة الفنية لخدمات السلامة والفحص الفني ش.م.م
SAFETY TECHNICAL SERVICES AND INSPECTIONS
Tel :+968 24502589, Fax : +968 24590272. Email: stsi@safetyoman.com, Website: www.safetyoman.com
P.O. Box 3288, Airport Heights P.C. 111, Sultanate of Oman.

LEEA Full Member

MAGNETIC PARTICLE INSPECTION REPORT

Date of Thorough Examination: 30/06/2022	**Report number:** MP/48939/22/06/15	**Job no:** 48939

Name and Address of the Owner of the Equipment **TRUCK OMAN - NORTH** **SULTANATE OF OMAN**	**Address of premises at which the examination was made:** **SAFAH**

Method: WET **Material: Carbon Steel** **Test temperature: Ambient**
Surface Condition: Acceptable **Equipment: Permanent magnet Yoke**

Area Inspected (tick the appropriate box):

☐ Weldment areas ☐ Stress Areas ☐ Full Body ☑ Others [TOP SURFACE ONLY]

WHITE CONTRAST PAINT: Magnavis WCP	**MAGNETISING METHOD: Wet suspension black ink**
BLACK MAGNETIC INK: Magnaflux 7HF	**ACCEPTANCE CODE: ASME V ARTICLE 7 , ASTM E709 ,AWS D1.1**

Description and identification of the equipment:

<u>FIFTH WHEEL</u>

Make: JOST

Type: JSK 38C

Reg no: 8809 MD / TO 600

Qty: 1 no

Date of Last MPI/ Cert No(If any): 14/07/2021 ; MA/46788/40

Result of the above test :

MPI TEST CARRIED OUT SATISFACTORILY, FOUND NO RELEVANT INDICATIONS AT THE TIME OF INSPECTION

Inspected by, Name & Signature : **Madhu Pillai** **Qualification : ASNT L2**		**Latest date by which next MPI must be carried out:** **29/06/2023**
Name and address of employer of persons making and authenticating this report: Address: SAFETY TECHNICAL SERVICES AND INSPECTIONS P.O. Box 3288. Airport Heights PC 111 Sultanate of Oman. lifting@safetyoman.com		SAFETY TECHNICAL SERVICES & INSPECTIONS LLC CERTIFIED