

## MAGNETIC PARTICLE INSPECTION REPORT

Date of Thorough Examination: 28/12/2025	Report number: MN/5692/25/12/04	Job no: 5692
Name and Address of owner for whom the thorough examination was made:  TRUCK OMAN EQUIPMENT RENTAL LLC SULTANATE OF OMAN		Address of premises at which the examination was made:  ADAM
Method: WET Surface Condition: Acceptable	Material: Carbon Steel Equipment: Permanent magnet Yoke	Test temperature: Ambient
Area Inspected (tick the appropriate box):  Weldment areas <input type="checkbox"/> Stress Areas <input type="checkbox"/> Full Body <input checked="" type="checkbox"/> Others [ TOP SURFACE]		
WHITE CONTRAST PAINT: Magnavis WCP	MAGNETISING METHOD: Wet suspension black ink	
BLACK MAGNETIC INK: Magnaflux 7HF	ACCEPTANCE CODE: ASME V ARTICLE 7, ASTM E709, AWS D1.1	
Description and identification of the equipment:  <u>FIFTH WHEEL</u>  Make: JOST  Type: JSK 38C  Serial no: 15739721 63  Reg no: 1769 BM  Fleet No: TO 2066  Qty: 1 no		
Date of Last MPI/ Cert No (If any): <b>VG/4230/25/07/05</b>		
Result of the above test:  <b>MPI TEST CARRIED OUT SATISFACTORILY, FOUND NO RELEVANT INDICATIONS AT THE TIME OF INSPECTION</b>		
Inspected by, Name & Signature: MIDHUN CS  Qualification: ASNT L2		Latest date by which next MPI must be carried out: 27/06/2026
Name and address of employer of persons making and authenticating this report:  <b>Address: SAFETY TECHNICAL SERVICES AND INSPECTIONS P.O. Box 3288. Airport Heights PC 111 Sultanate of Oman. lifting@safetyoman.com</b>		