



MAGNETIC PARTICLE INSPECTION REPORT

REPORT No.: AUG21/6048/MP1/C4


DATE OF INSPECTION: 5 August 2021

NAME AND ADDRESS OF THE OWNER AND CLIENT (IF OWNER IS NOT THE CLIENT)	CLIENT - ARABIAN ENGINEERING SERVICES OWNER - TRUCKOMAN LLC		
PLACE OF INSPECTION	GHALA		
I SAFETY WORK INSTRUCTION	WI-QMS-P011-019	TECHNIQUE	CONTINUOUS
REFERENCE CODE	AWS D1.1	METHOD	WET VISIBLE
ACCEPTANCE CRITERIA	AWS D1.1 PARTC CLAUSE 6.10	BACKGROUND	MR CHEME 72
MATERIAL	CS	DETECTING MEDIA	MR CHEME 76S
SURFACE	AS CLEANED	EQUIPMENT DETAILS	EECI

DESCRIPTION OF EQUIPMENT

FIFTH WHEEL

TO 2071



PRIME MOVER DETAILS

CHASSIS NUMBER: WMA34WZZ5MM884203
REGISTRATION NUMBER: ---

FIFTH WHEEL DETAILS

MAKE: JOST
SERIAL No.: 15687265 63
SIZE: 3.5"

RESULT

ACCEPTED. NO RELEVANT INDICATIONS FOUND ON THE FIFTH WHEEL

DETAILS OF PREVIOUS INSPECTION

NEW

DATE OF NEXT INSPECTION

4 August 2022


NAME AND POSITION OF PERSON WHO CARRIED OUT
THE INSPECTION AND TEST

MOHAMMED RIZWAN AHMED

INSPECTION ENGINEER (ASNT LEVEL II)



This certificate/report is granted subject to the condition that is understood and agreed that nothing herein contained shall be deemed to relieve any designer, manufacturer, seller, supplier, repairer or operator of any warranty, express or implied, and Integrated Safety International Services liability shall be limited to the acts or omissions of its employees, agents and subcontractors. Under no circumstances whatsoever shall Integrated Safety International Services be liable for any injury or damage to any person or occurring due negligent operation or any defect in materials, machinery, equipment or other items other than such defects ascertainable by normally accepted standards and only those items inspected by Integrated Safety International Services and which are covered by this certificate. This certificate/report shall not be reproduced except in the full without the approval of the inspection body and the client. Inspection results relate exclusively to the work ordered, the item(s) or the lot inspected.



INTEGRATED SAFETY INTERNATIONAL SERVICES LLC

IPO Box 1309, PC 130, Azaiba, Sultanate of Oman | C.R. 1239519 | Tel: 24349902 | Email: info@isafety.co | Website: www.isafety.co |