

## MAGNETIC PARTICLE INSPECTION REPORT

Date of Thorough Examination: 25/06/2023	Report number: MP/51271/23/06/121	Job no: 51271
Name and Address of owner for whom the thorough examination was made: TRUCK OMAN SULATANATE OF OMAN		Address of premises at which the examination was made: NIMR
Method: WET Surface Condition: Acceptable	Material: Carbon Steel Equipment: Permanent magnet Yoke	Test temperature: Ambient
Area Inspected ( tick the appropriate box):  <input type="checkbox"/> Weldment areas <input type="checkbox"/> Stress Areas <input type="checkbox"/> Full Body <input checked="" type="checkbox"/> Others [TOP SURFACE ONLY]		
WHITE CONTRAST PAINT: Magnavis WCP	MAGNETISING METHOD: Wet suspension black ink	
BLACK MAGNETIC INK: Magnaflux 7HF	ACCEPTANCE CODE: ASME V ARTICLE 7 , ASTM E709 ,AWS D1.1	
Description and identification of the equipment:  <b>FIFTH WHEEL</b>  Make: JOST Type: JSK 38C Serial No. : 1569105663 Reg No. : 116 MS Owner Fleet No: TO 2073 Qty : 1 No.		
Date of last MPI / Certificate No. (If any): 16/07/2022;MP/48942/22/07/38		
Result of the above test :  <b>MPI TEST CARRIED OUT SATISFACTORILY, FOUND NO RELEVANT INDICATIONSAT THE TIME OF INSPECTION</b>		
Inspected by, Name & Signature : MADHU PILLAI  Qualification : ASNT L2		Latest date by which next MPI must be carried out: 24/06/2024
Name and address of employer of persons making and authenticating this report:  <b>Address: SAFETY TECHNICAL SERVICES AND INSPECTIONS P.O. Box 3288. Airport Heights PC 111 Sultanate of Oman. <a href="mailto:lifting@safetyoman.com">lifting@safetyoman.com</a></b>		

