



AN ISO/IEC 17020 ACCREDITED INSPECTION BODY

CERTIFICATE OF THOROUGH EXAMINATION AND TEST

Certificate No: MP/51271/23/06/103

Date of Inspection: 24/06/2023

Name and Address of the Owner:	TRUCK OMAN
Maker & Date of Manufacture:	VOLVO 2020
Place of Inspection:	NIMR
Ref. Standard:	BS ISO2330 /BS EN 474-3/SP2275
Registration No. & Owner No.:	2862 MS; T02545
Model No. and Serial No.:	L70F-VCEOL70FP00072711
Running hours:	2667 Hrs
Manufacturer's documentation:	YES
Date of Previous inspection / cert no:	07/01/2023;MP/49842
Date of Next inspection:	23/12/2023
Date of Previous load test / cert no:	07/01/2023;MP/49842
Date of Next load test:	06/01/2024
Availability of operations manual in cabin:	YES
Availability of daily check report:	YES

Description of Forklift:

Diesel powered hydraulic articulated wheel loader fork lift with side shifter SWL: 5000 kgs @ 600 mm load center.

Test carried out according to tabulated column

Description of test:	Test load applied In (t)	S.W.L In (t)
	5.0 t	5.0 t
Visual inspection, Functional test & Performance test carried out.		
Max. Lifting Height: 3280 mm		
Hydraulic creep : Nil		
Fork Serial No.: 3272(L), 3278(R)		

Conclusion: Fit for its intended use at the time of inspection. / Refer to checklist- Annexure of certificate

This certificate becomes invalid if any Alteration/Major Repair and modification is done.

This is to certify that the undersigned competent representative, did attend to examine the item described above in accordance to the aforementioned standard. At the time of inspection, the said item were found to be free from flaws, deformations or other defects. The equipment is satisfactory for its intended use within the limits specified and at the time of inspection was found to be satisfactory for further use, provided there is continuous maintenance applied, qualified operators employed and implementation of our remarks and recommendations.

Reviewed by, Name & Signature: Sandeep KP

Inspected by, Name & Signature: Madhu Pillai





AN ISO/IEC 17020 ACCREDITED INSPECTION BODY

ANNEXURE OF CERTIFICATE OF TEST & THOROUGH EXAMINATION

Certificate No: MP/51271/23/06/103

Date of Inspection: 24/06/2023

Status Legend: S- Satisfactory NA-Not applicable F-Findings CF-Critical Findings					
No.	Description	Status	No.	Description	Status
1	Operations Manual/Catalogue	S	17	All gauges in cab	S
2	Monthly Inspection record	S	18	Overhead & foot guard	S
3	Maintenance records	S	19	Exhaust system	S
4	OEM Specification plate	S	20	Side shifting function (if applicable)	NA
5	Tires, rims, wheel bolts and axles	S	21	Horn, reverse alarm, rotating warning light	S
6	Masts and Back rest , carriage	S	22	Lights & indicators	S
7	Forks and its extensions, slide end stopper, locks	NA	23	Seat and seat belts	S
8	Load chain and its assemblies	NA	24	Parking brake and foot brake function	S
9	Side rollers and roll over cage	NA	25	Fire extinguisher	S
10	Safety devices	S	26	Display markings (SWL, tire pressure, insp. date, due date)	S
11	Battery and its connections	S	27	Full functional test	S
12	Hydraulic system & hoses and end fittings	S	28	Rated load test	S
13	Electrical system & Cables	S	29	Overload test	NA
14	Cooling system	S	30	NDT(If applicable)	S
15	Steering function	S	31	Other Test (If applicable)	NA
16	All controls levers function & symbols legible	S	32	General Condition	S
Details of tools/equipments used:					
Findings/Critical Findings Report					
F/CF	No.	Remarks			
-	30	15/07/2022; MP/48942/22/07/42 14.07.2023 due			

