

الشركة الفنية لخدمات السلامة والفحص الفني ش.م.م.
SAFETY TECHNICAL SERVICES AND INSPECTIONS

Tel :+968 24502589, Fax : +968 24590272. Email: stsi@safetyoman.com, Website: www.safetyoman.com
P.O. Box 3288, Airport Heights P.C. 111, Sultanate of Oman.



CERTIFICATE OF THOROUGH EXAMINATION OF POWER DRIVEN WINCHES

Date of Thorough Examination: 22/11/2022	Report number: MP/49823/22/11/32	Job no: 49823
Name and Address of the Owner of the Equipment TRUCK OMAN SULTANATE OF OMAN		Address of premises at which the examination was made: SAFAH
<p>Description and identification of the equipment:</p> <p><u>BRADEN WINCH MOUNTED ON A TRUCK</u></p> <p>Fleet no. : TO 2326</p> <p>Model no.: HP130A</p> <p>Makers Serial no. : 2100008</p> <p>Hauling load or maximum tension load : 130,000 LBS</p> <p>Power Source : Hydraulic</p> <p>Winch System Direction : SOFT EYE</p> <p>Wire rope : 28mmØ x 50mtr steel wire rope fitted with Roll-lock and 26mm chain and grab hook BN- 48110/5</p> <p>Location : Kenworth – 894 BM</p> <p>Visual inspection and Functional test carried out.</p>		
Date of Previous Examination/ cert no: 16/03/2022; MP/48138/22/03/03	Date of Next Examination: 21/05/2023	
Date of Previous Test/ cert no: NA	Date of Next Test: NA	
Ref. Standards: BS EN 14492-1		
Comments(if any): Refer Annex for Checklist		
<p>RESULT: The above mentioned equipment was found to be in order for its intended use at the time of inspection.</p> <p><i>This certificate becomes invalid if any Alteration/Major Repair and modification is done.</i></p> <p>This is to certify that the undersigned competent representative, did attend to examine the item described above in accordance to the aforementioned standard. At the time of inspection, the said item were found to be free from flaws, deformations or other defects. The equipment is satisfactory for its intended use within the limits specified and at the time of inspection was found to be satisfactory for further use, provided there is continuous maintenance applied, qualified operators employed and implementation of our remarks and recommendations.</p>		

Approved by, Name & Signature: Infano Oswin



Inspected by, Name & Signature: Madhu Pillai





الشركة الفنية لخدمات السلامة والفحص الفني ش.م.م.
SAFETY TECHNICAL SERVICES AND INSPECTIONS

Tel : +968 24502589, Fax : +968 24590272. Email: stsi@safetyoman.com, Website: www.safetyoman.com
P.O. Box 3288, Airport Heights P.C. 111, Sultanate of Oman.



Annexure of Report of Thorough Examination of Power driven Winches

Certificate No: MP/49823/22/11/32

Date of Inspection: 22/11/2022

SECTION	✓	X	REMARKS
Structural Frame/Dogging Fixture	✓		
Drums/Sheaves/Pulleys	✓		
Wire Rope	✓		
Wire Rope Termination/ Structures	✓		
Ratchet & Pawl/Braking& Clutches	✓		
Electric Cables	X		
Hooking Devices	✓		
Operational Control Devices	✓		
General Maintenance	✓		
Name Plate/Safety Instructions	✓		
Cleanliness & Upkeep	✓		
Swivel / Boomer Chain / Accessories	✓		

Inspected by, Name & Signature
Madhu Pillai

Approved by, Name & Signature
Infanso Oswin

Name and address of employer of persons making and authenticating this report:

Address: SAFETY TECHNICAL SERVICES AND INSPECTIONS
P.O. Box 3288. Airport Heights PC 111 Sultanate of Oman.
lifting@safetyoman.com



For certificate authenticity or for further clarifications, please contact us at stsi@safetyoman.com

A part of SAFETY *technical* SERVICES group



الشركة الفنية لخدمات السلامة والفحص الفني ش.م.م

SAFETY TECHNICAL SERVICES AND INSPECTIONS

Tel: +968 24502589, Fax: +968 24590272, Email: stsi@safetyoman.com, Website: www.safetyoman.com
P.O. Box 3288, Airport Heights P.C. 111, Sultanate of Oman.

CERTIFICATE OF VISUAL INSPECTION

WINCH WIRE ROPE
CHANCE



Customer No: SA/50522/22/12/01
Name and Address of the Owner of the Equipment

TRUCKOMAN (OXY)
SULTANATE OF OMAN

Report no: 50520

Address of premises at which the examination was made:
JIFNAIN
Colour code (if required): YELLOW

Identification Number	Location	Description	WLL or SWL	Date of Last Thorough Examination	Date of this Thorough Examination	Latest date of the Next Thorough Examination	Ref.Standard	Safe to Use Yes or No
BN 48110/1	STORE	28mm X 50M Steel Wire Rope Slings One End Soft Eye t/w Crosby Tail Chain and other end t/w Aluminium Stopper	547KN (MBL)	28/01/2022 AZ/RT/22/11/37562	14/12/2022	13/06/2023	BS EN 13414 – 1 SP2275	YES
BN 48110/2	STORE	28mm X 50M Steel Wire Rope Slings One End Soft Eye t/w Crosby Tail Chain and other end t/w Aluminium Stopper	547KN (MBL)	01/09/2022 AZ/RT/22/09/36701	14/12/2022	13/06/2023	BS EN 13414 – 1 SP2275	YES
BN 48110/3	STORE	28mm X 50M Steel Wire Rope Slings One End Soft Eye t/w Crosby Tail Chain and other end t/w Aluminium Stopper	547KN (MBL)	01/09/2022 AZ/RT/22/09/36701	14/12/2022	13/06/2023	BS EN 13414 – 1 SP2275	YES
BN 48110/4	STORE	28mm X 50M Steel Wire Rope Slings One End Soft Eye t/w Crosby Tail Chain and other end t/w Aluminium Stopper	547KN (MBL)	01/09/2022 AZ/RT/22/09/36701	14/12/2022	13/06/2023	BS EN 13414 – 1 SP2275	YES
BN 48110/5	STORE	28mm X 50M Steel Wire Rope Slings One End Soft Eye t/w Crosby Tail Chain and other end t/w Aluminium Stopper	547KN (MBL)	01/09/2022 AZ/RT/22/09/36701	14/12/2022	13/06/2023	BS EN 13414 – 1 SP2275	YES
Details of tools/equipment's used: STS-LD-91, 93								
Inspected by, Name & Signature : SULAIMAN AL-ANBORI			Approved By, Name & Signature: INFANSO OSWIN					
			Address: SAFETY TECHNICAL SERVICES AND INSPECTIONS P.O. Box 3288, Airport Heights PC 111 Sultanate of Oman. lifting@safetyoman.com					

The inspection certificate shall not be reproduced except in full without the approval of the inspection body and the client.
Inspection is performed only related to the work ordered (the items or the lot inspected).
For certificate authenticity and clarifications contact us at info@safetyoman.com