

## MAGNETIC PARTICLE INSPECTION REPORT

Date of Inspection: 20/08/2023	Report number: MP/51293/23/09/56	Job no: 51293
Name and Address of the Owner of the Equipment TRUCK OMAN EQUIPMENT RENTAL SULTANATE OF OMAN		Address of premises at which the examination was made: ADAM
Method: WET Surface Condition: Acceptable	Material: Carbon Steel Equipment: Permanent magnet Yoke	Test temperature: Ambient
Area Inspected ( tick the appropriate box):  <input checked="" type="checkbox"/> Weldment areas <input type="checkbox"/> Stress Areas <input type="checkbox"/> Full Body <input type="checkbox"/> Others		
WHITE CONTRAST PAINT: Magnavis WCP	MAGNETISING METHOD: Wet suspension black ink	
BLACK MAGNETIC INK: Magnaflux 7HF	ACCEPTANCE CODE: ASME V ARTICLE 7, ASTM E709, AWS D1.1	
Description and identification of the equipment:  <u>CRUDE OIL TANK SKID C/W 4NOS. LIFTING LUGS AT BOTTOM CORNERS MADE UP OF 6" STEEL PIPE.</u>		
Fleet No. : TER 1900		
MPI spots : A to D at bottom corners		
Qty: 4nos.		
Date of Last MPI/ Cert No( If any): 16/08/2022; MP/49806		
Result of the above test :  <b>MPI TEST CARRIED OUT SATISFACTORILY, FOUND NO RELEVANT INDICATIONS AT THE TIME OF INSPECTION</b>		

Inspected by, Name & Signature : Madhu Pillai  Qualification : ASNT L2		Latest date by which next MPI must be carried out: 19/08/2024
Name and address of employer of persons making and authenticating this report:  <b>Address: SAFETY TECHNICAL SERVICES AND INSPECTIONS P.O. Box 3288. Airport Heights PC 111 Sultanate of Oman. <a href="mailto:lifting@safetyoman.com">lifting@safetyoman.com</a></b>		

