

MAGNETIC PARTICLE INSPECTION REPORT

[illegible]

Inspected by, Name & Signature: Madhu Pillai Qualification: ASNT L2		Latest date by which next MPI must be carried out: 09-01-2024
Name and address of employer of persons making and authenticating this report: Address: SAFETY TECHNICAL SERVICES AND INSPECTIONS P.O. Box 3288. Airport Heights PC 111 Sultanate of Oman. lifting@safetyoman.com		

