



MAGNETIC PARTICLE INSPECTION REPORT

Date of Inspection: 05/02/2026	Report number: K/7010/26/02/01	Job no: 7010
Name and Address of the Owner of the Equipment TRUCK OMAN EQUIPMENT RENTAL SULTANATE OF OMAN		Address of premises at which the examination was made: AL BURAYMI
Method: WET Surface Condition: Acceptable	Material: Carbon Steel Equipment: Permanent magnet Yoke	Test temperature: Ambient
Area Inspected (tick the appropriate box): <input checked="" type="checkbox"/> Weldment areas <input type="checkbox"/> Stress Areas <input type="checkbox"/> Full Body <input type="checkbox"/> Others		
WHITE CONTRAST PAINT: Magnavis WCP	MAGNETISING METHOD: Wet suspension black ink	
BLACK MAGNETIC INK: Magnaflux 7HF	ACCEPTANCE CODE: ASME V ARTICLE 7, ASTM E709, AWS D1.1	
Description and identification of the equipment: CRUDE OIL TANK SKID C/W 4NOS. LIFTING LUGS AT BOTTOM CORNERS MADE UP OF 6" STEEL PIPE.		
Fleet No.: TER 1911		
MPI spots id nos : A,B,C,D at bottom corners		
Qty: 4nos.		
Date of Last MPI/ Cert No (If any): 24.07.2025; AT4484.25.07.05		
Result of the above test: MPI TEST CARRIED OUT SATISFACTORILY, FOUND NO RELEVANT INDICATIONS AT THE TIME OF INSPECTION		

Inspected by Name & Signature: KOSHY MATHEW Qualification: ASNT L2		Latest date by which next MPI must be carried out: 04/08/2026
Name and address of employer of persons making and authenticating this report: Address: SAFETY TECHNICAL SERVICES AND INSPECTIONS P.O. Box 3288. Airport Heights PC 111 Sultanate of Oman. lifting@safetyoman.com		


MAGNETIC PARTICLE INSPECTION REPORT

Date of Inspection: 05/02/2026	Report number: K/7010/26/02/03	Job no: 7010
Name and Address of the Owner of the Equipment TRUCK OMAN EQUIPMENT RENTAL SULTANATE OF OMAN		Address of premises at which the examination was made: AL BURAYMI
Method: WET Surface Condition: Acceptable	Material: Carbon Steel Equipment: Permanent magnet Yoke	Test temperature: Ambient
Area Inspected (tick the appropriate box): <input checked="" type="checkbox"/> Weldment areas <input type="checkbox"/> Stress Areas <input type="checkbox"/> Full Body <input type="checkbox"/> Others		
WHITE CONTRAST PAINT: Magnavis WCP	MAGNETISING METHOD: Wet suspension black ink	
BLACK MAGNETIC INK: Magnaflux 7HF	ACCEPTANCE CODE: ASME V ARTICLE 7, ASTM E709, AWS D1.1	
Description and identification of the equipment: CRUDE OIL TANK SKID C/W 4NOS. LIFTING LUGS AT BOTTOM CORNERS MADE UP OF 6" STEEL PIPE.		
Fleet No.: TER 1909		
MPI spots id nos : A,B,C,D at bottom corners		
Qty: 4nos.		
Date of Last MPI/ Cert No (If any): 24.07.2025; AT4484.25.07.05		
Result of the above test: MPI TEST CARRIED OUT SATISFACTORILY, FOUND NO RELEVANT INDICATIONS AT THE TIME OF INSPECTION		

Inspected by Name & Signature: KOSHY MATHEW Qualification: ASNT L2		Latest date by which next MPI must be carried out: 04/08/2026
Name and address of employer of persons making and authenticating this report: Address: SAFETY TECHNICAL SERVICES AND INSPECTIONS P.O. Box 3288. Airport Heights PC 111 Sultanate of Oman. lifting@safetyoman.com		

MAGNETIC PARTICLE INSPECTION REPORT

Date of Inspection: 05/02/2026	Report number: K/7010/26/02/02	Job no: 7010
Name and Address of the Owner of the Equipment TRUCK OMAN EQUIPMENT RENTAL SULTANATE OF OMAN		Address of premises at which the examination was made: AL BURAYMI
Method: WET Surface Condition: Acceptable	Material: Carbon Steel Equipment: Permanent magnet Yoke	Test temperature: Ambient
Area Inspected (tick the appropriate box): <input checked="" type="checkbox"/> Weldment areas <input type="checkbox"/> Stress Areas <input type="checkbox"/> Full Body <input type="checkbox"/> Others		
WHITE CONTRAST PAINT: Magnavis WCP	MAGNETISING METHOD: Wet suspension black ink	
BLACK MAGNETIC INK: Magnaflux 7HF	ACCEPTANCE CODE: ASME V ARTICLE 7, ASTM E709, AWS D1.1	
Description and identification of the equipment: CRUDE OIL TANK SKID C/W 4NOS. LIFTING LUGS AT BOTTOM CORNERS MADE UP OF 6" STEEL PIPE.		
Fleet No.: TER 1908		
MPI spots id nos : A,B,C,D at bottom corners		
Qty: 4nos.		
Date of Last MPI/ Cert No (If any): 24.07.2025; AT4484.25.07.05		
Result of the above test: MPI TEST CARRIED OUT SATISFACTORILY, FOUND NO RELEVANT INDICATIONS AT THE TIME OF INSPECTION		

Inspected by Name & Signature: KOSHY MATHEW Qualification: ASNT L2		Latest date by which next MPI must be carried out: 04/08/2026
Name and address of employer of persons making and authenticating this report: Address: SAFETY TECHNICAL SERVICES AND INSPECTIONS P.O. Box 3288. Airport Heights PC 111 Sultanate of Oman. lifting@safetyoman.com		