

MAGNETIC PARTICLE INSPECTION REPORT

Date of Inspection: 11/08/2021	Report number: O/47031/21/08/31	Job no: 47031
Name and Address of the Owner of the Equipment TRUCK OMAN NORTH SULTANATE OF OMAN		Address of premises at which the examination was made: ADAM
Method: WET Surface Condition: Acceptable	Material: Carbon Steel Equipment: Permanent magnet Yoke	Test temperature: Ambient

Area Inspected (tick the appropriate box):

Weldment areas Stress Areas Full Body Others

WHITE CONTRAST PAINT: Magnavis WCP	MAGNETISING METHOD: Wet suspension black ink
------------------------------------	--

BLACK MAGNETIC INK: Magnaflux 7HF	ACCEPTANCE CODE: ASME V ARTICLE 7 , ASTM E709 ,AWS D1.1
-----------------------------------	---

Description and identification of the equipment:

Fork Heel , Upper & Lower Hooks

Make: Caterpillar

Reg no: 5142 WK

Owner id no: TO 2526

Fork Serial no: 371 2376
371 2377

Qty: 1 Pair

Date of Last MPI/ Cert No(If any): 06/09/2020; O/44490/29

Result of the above test :

MPI TEST CARRIED OUT SATISFACTORILY, FOUND NO RELEVANT INDICATIONS AT THE TIME OF INSPECTION

Inspected by, Name & Signature : Vijeesh Ravi		Latest date by which next MPI must be carried out: After One Year As Per Client Requirement Or At The Discretion Of Lifting Inspector
Qualification : ASNT L2		
Name and address of employer of persons making and authenticating this report: Address: SAFETY TECHNICAL SERVICES AND INSPECTIONS P.O. Box 3288. Airport Heights PC 111 Sultanate of Oman. lifting@safetyoman.com		

