



AN ISO/IEC 17020 ACCREDITED INSPECTION BODY

Certificate No: MP/42144/20/03/16

Date of Inspection: 03/20/2020

Name and Address of the Owner:	TRUCK OMAN (NORTH)
Maker & Date of Manufacture:	CATERPILLAR ; 2015
Place of Inspection:	ADAM
Ref. Standard:	ISO22915-2 /BS EN 1459/SP2275
Registration No. & Owner No.:	5142 WK ; TO-2526
Model No. and Serial No.:	930K ; CAT0930KPEYE00563
Running hours:	7358 hrs.
Manufacturer's documentation:	In service equipment
Date of Previous inspection / cert no:	MP/40940/19/09/37 04/09/2019
Date of Next inspection:	03/03/2020
Date of Previous load test / cert no:	23/12/2014 ; R28608/14/12/1
Date of Next load test:	11/02/2023
Availability of operations manual in cabin:	Available
Availability of daily check report:	Available

Description of Forklift:

Diesel powered hydraulic articulated forklift SWL : 5000 kgs @ 600mm load center,

Test carried out according to tabulated column

Description of test: Visual inspection, Functional test & Performance test carried out.	Test load applied In kgs	S.W.L In kgs
Max. Lifting Height : 3668mm	---	5000 kg
Hydraulic creep : Nil		
Fork Serial No. : 371-2377 (Pair)		

Conclusion: Fit for its intended use at the time of inspection.

Approved by, Name & Signature: Mr. Gishin Thomas

Inspected by, Name & Signature: Infanso Oswin

Ref: STS-FMT-03 Rev.01 Date: 27.01.2019



1/2



Annexure of certificate of test & thorough examination of Fork lift

Certificate No: MP/42144/20/03/16

Date of Inspection: 03/20/2020

Description	Condition	Remarks
Tires, rims, wheel bolts and axles	Satisfactory	
Masts and Back rest , carriage	Satisfactory	
Forks and its extensions, slide end stopper, locks	Satisfactory	
Load chain and its assemblies	Not Applicable	
Side rollers and roll over cage	Not Applicable	
Safety devices	Satisfactory	
Battery and its connections	Satisfactory	
Hydraulic system & hoses and end fittings	Satisfactory	
Electrical system & Cables	Satisfactory	
Cooling system	Satisfactory	
Steering function	Satisfactory	
All controls levers function & symbols legible	Satisfactory	
Capacity plate in place and legible	Satisfactory	
All gauges in cab	Satisfactory	
Over head & foot guard	Satisfactory	
Exhaust system	Satisfactory	
Side shifting function (if applicable)	Not Applicable	
Horn, reverse alarm, rotating warning light	Satisfactory	
Lights & indicators	Satisfactory	
Seat and seat belts	Satisfactory	
Parking brake and foot brake function	Satisfactory	
Fire extinguisher	Satisfactory	
MPI fork blades, date / report nr. (annually)	Satisfactory	03/09/2020- done
Mast disassembly (every 4 years)	Not Applicable	
General condition	Satisfactory	
Display markings (SWL, tire pressure, insp. date, due date)	Satisfactory	
Details of tools/equipments used: Measuring tape (STS-LD-75) ; Vernier Caliper (STS-LD-65)		

General comments: NONE

Approved by, Name & Signature: Mr. Gishin Thomas

Inspected by, Name & Signature: Infanso Oswin

